

因部分飞行器与遥控器固件未更新, D-RTK 3 所新增的错误码, 在DJI Pilot 2 中尚未适配显示故障信息和解决方案。

如搭配D-RTK 3 使用时 Pilot 2内提示 “未知错误, 请检查固件升级或联系大疆售后服务” 或 “系统发生错误, 请联系就近代理商或大疆售后服务”, 可找到具体故障代码, 在本文档查看对应故障信息及解决方案。

Due to the firmware of some devices not being updated, Pilot 2 has not adapted to the new information and solutions.

When used with D-RTK 3, if Pilot 2 displays or 'Unknown error. Update firmware or contact DJI Support' or 'System error. Contact your local dealer or DJI Support,' you can refer to this document to view the corresponding error information and solutions based on the specific error code.

故障代码/Error code	故障信息与解决方案/Error information and solutions								
	zh-cn	en	de	jp	fr	ko	ru	es	tr
0x160900C8	D-RTK3电池电量低于20%, 请及时充电	D-RTK 3 battery level below 20%. Charge promptly	D-RTK 3: Akkustand unter 20 %. Umgehend aufladen	D-RTK 3バッテリーの残量が20%未満です。直ちに充電してください	D-RTK 3 : niveau de batterie inférieur à 20 %. Rechargez la batterie dès que possible.	D-RTK 3 배터리 잔량이 20% 미만입니다. 즉시 충전하세요.	Уровень заряда аккумулятора D-RTK 3 ниже 20%. Не медленно зарядите АКБ	Nivel de batería de D-RTK 3 por debajo del 20 %. Cárguela cuanto antes	D-RTK 3 pilinin seviyesi %20'nin altında. Hemen şarj edin
0x160900C9	D-RTK3电池电量低于10%, 请及时充电	D-RTK 3 battery level below 10%. Charge promptly	D-RTK 3: Akkustand unter 10 %. Umgehend aufladen	D-RTK 3バッテリーの残量が10%未満です。直ちに充電してください	D-RTK 3 : niveau de batterie inférieur à 10 %. Rechargez la batterie dès que possible.	D-RTK 3 배터리 잔량이 10% 미만입니다. 즉시 충전하세요.	Уровень заряда аккумулятора D-RTK 3 ниже 10%. Не медленно зарядите АКБ	Nivel de batería de D-RTK 3 por debajo del 10 %. Cárguela cuanto antes	D-RTK 3 pilinin seviyesi %10'un altında. Hemen şarj edin
0x16090095	D-RTK3电池电压过高, 请尽快返航或降落重启电池	D-RTK 3 battery overcurrent during charging. Disconnect charging device and reconnect	Akkuspannung zu hoch. Umgehend zum Startpunkt zurückkehren oder landen. Fluggerät trennen und wieder anschließen	バッテリーの電圧が高すぎます。直ちに帰還するか、着陸してください。着陸後に機体を再起動してください	Tension de batterie trop élevée. Revenez au point de départ ou atterrissez dès que possible. Redémarrez l'appareil après l'atterrissage.	배터리 전압이 너무 높습니다. 리턴 투 홈을 실행하거나 즉시 착륙시키세요. 착륙 후 기체를 재시동하세요.	Слишком высокое напряжение аккумулятора. Как можно скорее выполните возврат домой или приземление. Перезапустите дрон после приземления	Voltaje de la batería demasiado alto. Regresa al punto de origen o aterriza rápidamente. Reinicia la aeronave después del aterrizaje.	Pil voltajı çok yüksek. Kalkış noktasına dönün veya derhal iniş yapın. İnişten sonra aracı yeniden başlatın
0x160900CA	D-RTK3电池充电过流, 请断开充电设备后重新连接	D-RTK 3 battery overcurrent during charging. Disconnect charging device and reconnect	D-RTK 3: Akku-Überstrom während des Ladevorgangs. Ladegerät trennen und wieder anschließen	充電中のD-RTK 3バッテリー過電流。充電中のデバイスを取り外して再接続してください	D-RTK 3 : surintensité de la batterie pendant la recharge. Débranchez le chargeur, puis reconnectez-le.	충전 중 D-RTK 3 배터리 과전류 현상입니다. 충전 기기를 분리하고 다시 연결하세요.	Сверхток аккумулятора D-RTK 3 при зарядке. Отсоедините зарядное устройство и переподключите его	Sobrecorriente de la batería de D-RTK 3 durante la carga. Desconecta el dispositivo de carga y vuelve a conectarlo	Şarj sırasında D-RTK 3 pilinde aşırı akım. Şarj cihazının bağlantısını kesin ve tekrar bağlayın
0x160900CB	D-RTK3电池放电过流, 请尝试重启	D-RTK 3 battery overcurrent during discharging. Restart D-RTK 3	D-RTK 3: Akku-Überstrom während der Entladung. D-RTK 3 neu starten	放電中のD-RTK 3バッテリー過電流。D-RTK 3を再起動します	D-RTK 3 : surintensité de la batterie pendant la décharge. Redémarrez D-RTK 3	방전 중 D-RTK 3 배터리 과전류 현상입니다. D-RTK 3 다시 시작	Сверхток аккумулятора D-RTK 3 во время разрядки. Перезапустите D-RTK 3	Sobrecorriente de la batería de D-RTK 3 durante la descarga. Reiniciar la D-RTK 3	Deşarj sırasında D-RTK 3 pilinde aşırı akım. D-RTK 3'ü Yeniden Başlat
0x160900CD	D-RTK3电池温度大于70°C, 请待电池冷却到常温后再使用	D-RTK 3 battery temperature exceeds 70° C. Wait for temperature to return to normal before use	D-RTK 3: Akku-Temperatur über 70° C. Vor der Verwendung warten, bis sich die Temperatur wieder normalisiert hat	D-RTK 3バッテリーの温度が70°Cを超えています。バッテリーの温度が正常に戻ってから使用してください	D-RTK 3 : la température de la batterie dépasse 70 ° C. Attendez que la température revienne à la normale avant de l'utiliser.	D-RTK 3 배터리 온도가 70°C를 초과합니다. 사용하기 전에 온도가 정상으로 돌아올 때까지 기다리세요.	Температура аккумулятора D-RTK 3 превышает 70 °С. Перед использованием подождите, пока температура вернется к норме	Temperatura de la batería de D-RTK 3 superior a 70 ° C. Espera a que vuelva a una temperatura normal antes de usarla	D-RTK 3 pilinin sıcaklığı 70°C'nin üstünde. Kullanmadan önce sıcaklığın normale dönmesini bekleyin
0x160900CE	D-RTK3电池温度大于75°C, 请待电池冷却到常温后再使用	D-RTK 3 battery temperature exceeds 75° C. Wait for temperature to return to normal before use	D-RTK 3: Akku-Temperatur über 75° C. Vor der Verwendung warten, bis sich die Temperatur wieder normalisiert hat	D-RTK 3バッテリーの温度が75°Cを超えています。バッテリーの温度が正常に戻ってから使用してください	D-RTK 3 : la température de la batterie dépasse 75 ° C. Attendez que la température revienne à la normale avant de l'utiliser.	D-RTK 3 배터리 온도가 75°C를 초과합니다. 사용하기 전에 온도가 정상으로 돌아올 때까지 기다리세요.	Температура аккумулятора D-RTK 3 превышает 75 °С. Перед использованием подождите, пока температура вернется к норме	Temperatura de la batería de D-RTK 3 superior a 75 ° C. Espera a que vuelva a una temperatura normal antes de usarla	D-RTK 3 pilinin sıcaklığı 75°C'nin üstünde. Kullanmadan önce sıcaklığın normale dönmesini bekleyin
0x160900D0	D-RTK3电池温度过低, 即将关机	Battery temperature too low. D-RTK 3 will power off	Akkutemperatur zu niedrig. D-RTK 3 schaltet sich aus	バッテリー温度が低すぎます。D-RTK 3の電源をオフにします	Température de la batterie trop faible. D-RTK 3 va s'éteindre.	배터리 온도가 너무 낮음. D-RTK 3의 전원이 꺼집니다.	Слишком низкая температура аккумулятора. D-RTK 3 отключится	Temperatura de la batería demasiado baja. D-RTK 3 se apagará	Pil sıcaklığı çok düşük. D-RTK 3 kapanacak
160B0000	D-RTK3多功能基站断开连接	D-RTK 3 multifunctional station disconnected	D-RTK 3 Multifunktionsstation nicht verbunden	D-RTK 3多機能ステーションの接続が切断されました	Station multifonction D-RTK 3 débranchée	D-RTK 3 다기능 스테이션 연결 끊김	Многофункциональная станция D-RTK 3 отключена	Estación multifunción D-RTK 3 desconectada	D-RTK 3 çok işlevli istasyonunun bağlantısı kesildi
0x160B0001	D-RTK3多功能基站位置移动	D-RTK 3 multifunctional station moved	D-RTK 3 Multifunktionsstation wurde bewegt	D-RTK 3多機能ステーションが移動しました	Station multifonction D-RTK 3 déplacée	D-RTK 3 다기능 스테이션 이동됨	Многофункциональная станция D-RTK 3 перемещена	Estación multifunción D-RTK 3 movida	D-RTK 3 çok işlevli istasyonu taşındı
0x160B0002	D-RTK3多功能基站RTK搜星异常, 请检查信号是否有遮挡, 并在搜星信号良好位置使用设备	D-RTK 3 multifunctional station RTK satellite signal searching error. Check if signal is obstructed and use device in area with strong satellite signal	D-RTK 3 Multifunktionsstation, RTK: Fehler bei Suche nach Satellitensignal. Prüfen, ob das Signal blockiert ist, und das Gerät in einem Bereich mit starkem Satellitensignal verwenden	D-RTK 3多機能ステーションのRTK衛星信号検索エラーです。信号が遮断されていないことを確認し、衛星信号が強い場所でデバイスを使用してください	Erreur de recherche du signal satellite RTK de la station multifonction D-RTK 3. Vérifiez si le signal est obstrué et utilisez l'appareil dans une zone où le signal satellite est puissant.	D-RTK 3 다기능 스테이션 RTK 위성 신호 검색 오류. 신호가 막혔는지 확인하고 위성 신호가 강한 장소에서 기기를 사용하세요.	Ошибка поиска спутников о сигнала RTK многофункциональной станции D-RTK 3. Проверьте, не нарушается ли сигнал, и используйте устройство в области с мощным спутниковым сигналом	Error de búsqueda de señal del satélite RTK de la estación multifunción D-RTK 3. Comprueba si la señal está obstruida y usa el dispositivo en una zona con una señal de satélite fuerte	D-RTK 3 çok işlevli istasyonu RTK uydusu sinyali arama hatası. Sinyalin engellenip engellenmediğini kontrol edin ve cihazı uydusu sinyalinin güçlü olduğu bir alanda kullanın
0x160B0003	D-RTK3多功能基站初始定位位置距离上次标定位置过远	Initialization position of D-RTK 3 multifunctional station is too far from last calibrated position	Initialisierungsposition der D-RTK 3-Multifunktionsstation ist zu weit von der zuletzt kalibrierten Position entfernt	D-RTK 3多機能ステーションの初期化位置が前回キャリブレーションした位置から離れすぎています	La position d'initialisation de la station multifonction D-RTK 3 est trop éloignée de la dernière position étalonnée.	D-RTK 3 다기능 스테이션의 초기화 위치가 마지막으로 캘리브레이션된 위치에서 너무 멉니다.	Положение инициализации и многофункциональной станции D-RTK 3 находится слишком далеко от последнего точно установленного положения	La posición de inicialización de la estación multifunción D-RTK 3 está demasiado lejos de la última posición calibrada	D-RTK 3 çok işlevli istasyonunun başlatma konumu son kalibre edilen konumdan çok uzakta
0x160B0004	D-RTK3多功能基站初始定位失败, 请移动至搜星信号良好位置重新部署	Failed to initiate D-RTK 3 multifunctional station positioning. Redeploy in area with strong satellite signal	Die Positionierung der D-RTK 3-Multifunktionsstation konnte nicht gestartet werden. In einem Bereich mit starkem Satellitensignal erneut versuchen	D-RTK 3多機能ステーションの測位の開始に失敗しました。衛星信号の強い場所に再配備してください	Échec du lancement du positionnement de la station multifonction D-RTK 3. Recommencez dans une zone où le signal satellite est puissant.	D-RTK 3 다기능 스테이션 포지셔닝을 시작하지 못했습니다. 위성 신호가 강한 장소에 재배치하세요.	Не удалось инициализировать позиционирование многофункциональной станции D-RTK 3. Переместите в область с мощным спутниковым сигналом	Fallo al iniciar el posicionamiento de la estación multifunción D-RTK 3. Vuelve a desplegarla en una zona con una señal de satélite fuerte	D-RTK 3 çok işlevli istasyonunun konumlandırması başlatılamadı. Uydusu sinyalinin güçlü olduğu bir alanda yeniden devreye alın
0x16070046	检测到电离层闪烁, RTK定位性能受影响, 请谨慎飞行	Ionospheric scintillation detected. RTK positioning performance affected. Fly with caution	Ionosphärische Szintillation erkannt. RTK-Positionierung beeinträchtigt. Vorsichtig fliegen	電離層シンチレーションを検出しました。RTK測位のパフォーマンスに影響しています。慎重に飛行してください	Scintillation ionosphérique détectée. Cela affecte les performances de positionnement RTK. Pilotez avec précaution.	전리층 섬광이 감지되었습니다. RTK 포지셔닝 성능이 영향을 받았습니다. 비행 시 주의 필요	Обнаружено ионосферное мерцание. Влияние на эффективность позиционирования RTK. Соблюдайте осторожность при полете	Centelleo ionosférico detectado. Rendimiento de posicionamiento RTK afectado. Vuela con cuidado	İyonosferik ışıldama tespit edildi. RTK konumlandırma performansı etkilendi. Dikkatli uçuş