

D-RTK 3 Release Notes

 Date:
 2025.02.27

 D-RTK 3 Firmware:
 v13.00.0004

 Matrice 4 Series Firmware:
 v12.01.06.06

 DJI RC Plus 2 Enterprise Firmware:
 v01.61.03.05

 DJI Pilot 2 App:
 v13.0.2.5

 DJI Assistant 2:
 v2.1.15

What's New

- Added support to D-RTK 3 Relay Fixed Deployment Version.
- Optimized the calibration performance of Custom Network RTK in D-RTK 3 Base Station mode.
- Updated the format after renaming the Bluetooth of the D-RTK 3 rover station.
- Updated some HMS alerts.
- Fixed the issue where, in the D-RTK 3 Base Station and Relay Station mode, if the Custom Network RTK calibration is terminated before completion and PPP calibration is triggered, the calibration interface does not display real-time calibration information and PPP calibration cannot be completed.
- Fixed the issue where the power indicator quickly turns off after pressing the power button when the battery is fully charged.
- Fixed the issue where the app occasionally reports a password error after entering the correct password.

Notes:

• Make sure that the aircraft, remote controller, and D-RTK 3 firmware are all updated to the latest version. Otherwise, usage will be affected.